

SITE ASSESSMENT REPORT

BUILDING 606, TANK 606

BASE REALIGNMENT AND CLOSURE

UNDERGROUND STORAGE TANK AND ABOVEGROUND STORAGE TANK GREY SITES

NAVAL AIR STATION CECIL FIELD JACKSONVILLE, FLORIDA

Unit Identification Code: N60200

Contract No.: N62467-89-D-0317/090

Prepared by:

Harding Lawson Associates 2590 Executive Center Circle, East Tallahassee, Florida 32301

Prepared for:

Department of the Navy, Southern Division Naval Facilities Engineering Command 2155 Eagle Drive North Charleston, South Carolina 29418

Bryan Kizer, Code 1842, Engineer-in-Charge

September 1998

Revision 0.0





CERTIFICATION OF TECHNICAL DATA CONFORMITY (MAY 1987)

The Contractor, Harding Lawson Associates, hereby certifies that, to the best of its knowledge and belief, the technical data delivered herewith under Contract No. N62467-89-D-0317/090 are complete and accurate and comply with all requirements of this contract.

DATE: September 9, 1998	
-------------------------	--

NAME AND TITLE OF CERTIFYING OFFICIAL:

Rao Angara

Task Order Manager

NAME AND TITLE OF CERTIFYING OFFICIAL:

Eric A. Blomberg, P.G. Project Technical Lead

(DFAR 252.227-7036)

TABLE OF CONTENTS

Site Assessment Report Building 606, Tank 606 Naval Air Station Cecil Field Jacksonville, Florida

Chapt	ter	T:	t1	e										Page	No.
1.0	INTRODUCTION													•	1
2.0	FIELD INVESTIGATION														1
3.0	SCREENING AND ANALYTICAL RESULTS		•				•	•	•	•					1
4.0	CONCLUSIONS AND RECOMMENDATIONS								•		•		•	•	5
REFE	RENCES														
APPE	NDICES														
-	opendix A: Closure Assessment Rep opendix B: Soil Analytical Data	poı	t												

LIST OF FIGURES

Site Assessment Report Building 606, Tank 606 Naval Air Station Cecil Field Jacksonville, Florida

Figu	re			<u> Title</u>											Page	<u>No</u>						
1	Tomle	606	Enlighed Dining Wall																			2
Τ	lank	606,	Enlisted Dining Hall .	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	4
2	Tank	606,	Soil Boring Locations																		•	3

LIST OF TABLES

Table	e Title Pag	e No
	Soil Screening Results	
2	Summary of Subsurface Soil Analytical Detections	6

The second

GLOSSARY

ABB-ES ABB Environmental Services, Inc

bls below land surface

FAC Florida Administrative Code

FDEP Florida Department of Environmental Protection

HLA Harding Lawson Associates

KAG Kerosene Analytical Group

OVA organic vapor analyzer

ppm parts per million

UST underground storage tank

yd³ cubic yard

1.0 INTRODUCTION

Harding Lawson Associates (HLA), under contract to the Southern Division, Naval Facilities Engineering Command, has completed the site assessment for Tank 606 at Naval Air Station Cecil Field in Jacksonville, Florida. This report summarizes the related field operations, results, conclusions, and recommendations of the site assessment.

Tank 606 was an underground storage tank (UST) located at Building 606, which was the Enlisted Dining Hall for the Marine Barracks in Yellow Water Weapons Area (Figure 1). The UST had a 3,000 gallon capacity and was used to store fuel oil for on-site heating. It is not known when the tank was installed.

Tank 606 was removed by Supship Portsmouth Environmental Detachment on April 15, 1997. Approximately 20 cubic yards (yd^3) of excessively contaminated soil was removed from the site at that time. Excessively contaminated soil was still present after the tank and 20 yd^3 of soil were removed. No groundwater contamination was detected in the groundwater sample collected from a temporary monitoring well that was installed in the area of the highest contamination. A closure report was prepared for Tank 606 and submitted to the Florida Department of Environmental Protection (FDEP) (Environmental Detachment Charleston, 1997). Since excessively contaminated soil remained after tank removal, a site assessment for the assessment of soil at Tank 606 was proposed.

2.0 FIELD INVESTIGATION


The site assessment for Tank 606 was initiated in November 1997 and included

- the advancement of 14 soil borings to the water table, and
- the collection of two subsurface soil samples.

Soil samples were collected from each boring at depth intervals of 1 foot below land surface (bls) and every 2 feet thereafter to the water table. These samples were screened for hydrocarbon vapors with an organic vapor analyzer (OVA). Two subsurface soil samples were collected from the areas with the highest OVA concentrations and analyzed for Kerosene Analytical Group (KAG) parameters. Samples CEF-606-SB1 and CEF-606-SB2 were collected from 2 to 4 feet bls and 3.5 feet bls, respectively.

3.0 SCREENING AND ANALYTICAL RESULTS

Excessively contaminated soil (greater than 50 parts per million [ppm] on an OVA) was detected in several soil borings. The highest OVA reading (1700 ppm) was detected at 3 feet bls from a moist sample collected from soil boring SB5. High levels of methane were also detected in the soil screening samples and may be causing the elevated OVA readings. Very few petroleum odors were identified in the soil samples. The extent of excessively contaminated soil is presented on Figure 2. The soil OVA data are summarized in Table 1.








Table 1 Soil Screening Results

Site Assessment Report Building 606, Tank 606 Naval Air Station Cecil Field Jacksonville, Florida

	OVA Concentration (ppm)								
Location	Depth (feet bis)	Unfiltered	Filtered	Actual					
SB1	1	50	25	25					
	3 (wet)	200	100	100					
SB2	1	1,900	1,650	250					
	3 (wet)	260	240	20					
SB3	1	0	0	0					
	3 (wet)	25	22	3					
SB4	1	3	0	3					
	3 (wet)	70	70	0					
SB5	1	50	15∖	35					
	3	2,000	300	1,700					
	4.5 (wet)	400	370	30					
SB6	1	20	4	16					
/	3	1,600	1,000	600					
	4.5 (wet)	1,800	1,800	0					
SB7	1	50	10	40					
	2 (wet)	20	0	20					
SB8	1	0	-	0					
	3 (wet)	140	120	20					
SB9	1	300	70 /	230					
	3 (wet)	15	70	0					
SB10	1	10	8	2					
<i>:</i>	3 (wet)	700	700	0					
SB11	1	1,200	150	1,050					
	3 (wet)	300	250	50					
SB12	1	0	0	0					
	3 (wet)	2,200	2,200	0					
SB13	1	1,000	1,000	0					
	3 (wet)	150	120	30					
SB14	1	50	50	0					
	3 (wet)	150	130	20					

Notes: All soil samples were collected on November 7 and 10, 1997.

All concentrations are in ppm.

Soil samples were filtered with carbon to determine the methane concentration.

OVA = organic vapor analyzer.

ppm = parts per million.

bis = below land surface.

wet = soil sample was completed saturated when analyzed.

- = filtered readings were not collected.

No contaminants were detected in the KAG soil samples above FDEP cleanup target levels as specified in Chapter 62-770, Florida Administrative Code (FAC). KAG soil sample results are summarized in Table 2. The complete analytical data set is presented in Appendix B.

4.0 CONCLUSIONS AND RECOMMENDATIONS

Data obtained during the site assessment at the Tank 606 site provided an adequate assessment of the horizontal and vertical extent of excessively contaminated soil. It appears that methane may be causing elevated OVA readings around the perimeter of the site, and delineation to 50 ppm was not completed. No contaminants were detected above the cleanup target levels specified in Chapter 62-770, FAC, in the KAG subsurface soil samples collected at the Tank 606 site. No contaminants were detected in the groundwater sample collected during the closure assessment. Therefore, it is recommended that no further action take place at the Tank 606 site.

Table 2 Summary of Subsurface Soil Analytical Detections

Site Assessment Report Building 606, Tank 606 Naval Air Station Cecil Field Jacksonville, Florida

Compound	CEF-606-SB1	CEF-606-SB2	Soil Cleanup Target Levels ¹
Volatile Organic Aromatics	(USEPA Method 8020) (mg/l	(g)	
No compounds detected			
Polynuclear Aromatic Hydro	ocarbons (USEPA Method 83	<u>10)</u> (mg/kg)	
Benzo(a)anthracene	0.033	ND	2.9
Benzo(a)pyrene	0.029	ND	7.8
Benzo(b)fluoranthene	0.032	ND	9.8
Benzo(g,h,i)perylene	0.020	ND	13,000
Benzo(k)fluoranthene	0.015	ND	25
Chrysene	0.028	ND	80
Dibenz(a,h)anthracene	0.028	ND	14
Fluoranthene	0.016	ND	550
Indeng(1,2,3-cd)pyrene	0.021	ND	28
Pyrene	0.077	ND	570
Total Recoverable Petroleum	m Hydrocarbons (TRPH) (FL-I	PRO) (mg/kg)	
TRPH	19	35	340

¹ Chapter 62-770, Florida Administrative Code for Leachability, Table V.

Notes: Soil sample was collected on April 16, 1998.

USEPA = U.S. Environmental Protection Agency.

mg/kg = milligrams per kilogram.

ND = not detected.

FL-PRO = Florida-Petroleum Residual Organics.



REFERENCES



Environmental Detachment Charleston. 1997. Closure Report for Underground Storage Tank 606, Naval Air Station Cecil Field, Jacksonville, Florida. (May).

APPENDIX A CLOSURE ASSESSMENT REPORT

Environmental Detachment Charleston 1899 North Hobson Avenue North Charleston, South Carolina 29405-2106

Eric Blomberg
ABB Environmental Engineering Services, Inc.
2590 Executive Center Circle East
Berkley Building
Tallahassee, Florida 32301

Dear Mr. Blomberg,

Enclosed are the Assessment Reports for five each UST's removed at NAS Cecil Field. The Assessment Reports are being forwarded per the request of Southern Division's Brian Kizer.

Respectfully,

Tom mess

Tom McElwee (Environmental Specialist)

SPORTENVDETCHASN SUPSHIP PORTSMOUTH ENVIRONMENTAL DETACHMENT CHARLESTON 1899 NORTH HOBSON AVENUE

NORTH CHARLESTON, S.C. 29405-2106



Underground Storage Tank (UST) Assessment Report

I OWNERSHIP OF UST(S)

Agency/Owner: Naval Air Station. Cecil Field DER Facility No. 168507293									
Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, NAS Cecil Field.									
City: Jacksonville State: FL Zip Code: 32215-0101									
Area Code: 9)4	Telephone Number:	778-5620	Contact Person:	Lloyd Cruz					

II SITE IDENTIFICATION AND LOCATION

Site I.D. #:	BUILDING 606								
Facility Name:	Naval Air Station Cecil Field								
Street Address:	Building 606. Main Road. Yell	Building 606, Main Road, Yellow Water Weapons Area							
City:	Jacksonville, 32215-0101	County:	Duval						

III CLOSURE INFORMATION

Closure Started: 4/15/97		Clos	sure Completed: 4/16/97
Numb N/A Consultant	per of USTs Closed:	<u> </u>	SPORTENVDETCHASN UST Removal Contractor

IV. CERTIFICATION (Read and Sign after completing entire submittal)

I certify that I have personally examined and am familiar with the information submitted in this and all attached documents; and that based on my inquiry of those individuals responsible for obtaining this information. I believe that the submitted information is true, accurate and complete. T.L. McElwee - Project Engineer
Name (Type or Print)
Signature

	V. UST INFORMATION	Tank l	Tank 2	Tank 3	Tank 4	Tank 5	Tank 6
4 .	Product	Fuel Oil					
3.	Capacity	3.000gai					
J.	Age	unk					
) .	Construction Material	steel					
Ξ.	Month/Year of Last Use	unk					
: ,	Depth (ft.) To Base of Tank	7'					
3 .	Spill Prevention Equipment Y/N	И	<u> </u>				
I.	Overfill Prevention Equipment Y/N	И					
	Method of Closure Removed/Filled	R	1				
•	Visible Corrosion or Pitting Y/N	Y	• .		_		2
ζ.	Visible Holes Y/N					 	l
. .	Method of disposal for any USTs removed fro	om the gro	ound (a	ttach di	sposal	manifes	ts)

UST 606 was removed, drained, cut open at both ends, and cleaned with a steam cleaner. It was then cut up for recycling as scrap metal and delivered to the Cecil Field Recycling Center. (See Attachment III.)

Method of disposal for any liquid petroleum, sludges, or waste waters removed from the M. USTs (attach disposal manifests)

> Prior to tank removal the residual fuel was pumped out of the tank by contractor. The disposal manifest is included in Attachment III. The oily rinse water was recycled through the oil/water separator at the Transportation Office, Building 80, NAS Cecil Field.

If any corrosion, pitting, or holes were observed, describe the location and extent for each N. **UST**

> The west side of the tank (street side) had many areas of corrosion and pitting, but only two holes were found. They were found midway up the side of the tank, 3 feet and 6 feet from the south end and a third hole was in the south end of the tank (supply and return end) approximately 1" from the bottom.

VI. PIPING INFORMATION

عد	5	٠ <u>٠</u> .	
Ċ	•	1,3	
1	٠	200	

	i	
A.	Construction Material	Steel & PVC
B.	Distance from UST to Dispenser	25' see note I
C.	Number of Dispensers	l see note l
D.	Type of System P/S	S
E.	Was Piping Removed from the Ground? Y/N	Y
F.	Visible Corrosion or Pitting Y/N	Y
G.	Visible Holes Y/N	Y
H.	Age	Unk
Note 1:	The tank provided fuel oil to Building 606.	

Tank 1

Tank 2 Tank 3

Tank 4

I. If any corrosion, pitting, or holes were observed, describe the location and extent for each line.

The supply and return piping had moderate corrosion and pitting. Several holes were found in the line between the tank and the building, and the mechanical connections at the tank were loose. The 1 ½" vent line from the tank was steel to a rubber boot and then polyvinyl chloride (PVC) piping to the side of the building. This vent piping had light corrosion with one 3/4" hole located just past the rubber boot in piping run. There was a second vent line that was entirely PVC and had been previously cut and abandoned at the edge of the excavation. This was removed. (See Site Map 4)

VII. BRIEF SITE DESCRIPTION AND HISTORY

Building 606 was a former Enlisted Men's Dining Facility located on Main Road in the Yellow Water Weapons area next to the barracks (building 605). A 3,000 gallon Fuel oil UST was located on the north side of the building and was used to provide fuel to a boiler that produced on site heat. The tank was 5'4" X 18' long and was located 7' deep under soil and asphalt.

VIII. SITE CONDITIONS

Yes No Unk

Were any petroleum-stained or contaminated soils found in the UST excavation, soil borings, trenches, or monitoring wells?			
If yes, indicate depth and location on the site map. [UST excavation from GSL to Concrete ballast pad @ 7', 3' deep in piping trenches and 2' to 6' deep in soil borings.]	х		
Were any petroleum odors detected in the excavation, soil borings, trenches, or monitoring wells?			
If yes, indicate location on site map and describe the odor (strong, mild, etc.) [Throughout UST excavation, strong]	X		
Was water present in the UST excavation, soil borings, or trenches? If yes, how far below land surface (indicate location and depth)?	:	х	
Did contaminated soils remain stockpiled on site after closure? If yes, indicate the stockpile location on the site map.			
		*X	
Was a petroleum sheen or free product detected on any excavation or boring waters?			
If yes, indicate location and thickness on the site map.		x	
	Excavation, soil borings, trenches, or monitoring wells? If yes, indicate depth and location on the site map. [UST excavation from GSL to Concrete ballast pad @ 7', 3' deep in piping trenches and 2' to 6' deep in soil borings.] Were any petroleum odors detected in the excavation, soil borings, trenches, or monitoring wells? If yes, indicate location on site map and describe the odor (strong, mild, etc.) [Throughout UST excavation, strong] Was water present in the UST excavation, soil borings, or trenches? If yes, how far below land surface (indicate location and depth)? Did contaminated soils remain stockpiled on site after closure? If yes, indicate the stockpile location on the site map. Was a petroleum sheen or free product detected on any excavation or boring waters?	Excavation. soil borings, trenches, or monitoring wells? If yes, indicate depth and location on the site map. [UST excavation from GSL to Concrete ballast pad @ 7', 3' deep in piping trenches and 2' to 6' deep in soil borings.] Were any petroleum odors detected in the excavation, soil borings, trenches, or monitoring wells? If yes, indicate location on site map and describe the odor (strong, mild, etc.) [Throughout UST excavation, strong] Was water present in the UST excavation, soil borings, or trenches? If yes, how far below land surface (indicate location and depth)? Did contaminated soils remain stockpiled on site after closure? If yes, indicate the stockpile location on the site map. Was a petroleum sheen or free product detected on any excavation or boring waters?	If yes, indicate depth and location on the site map. [UST escavation from GSL to Concrete ballast pad ② 7', 3' deep in piping trenches and 2' to 6' deep in soil borings.] Were any petroleum odors detected in the excavation, soil borings. trenches, or monitoring wells? If yes, indicate location on site map and describe the odor (strong, mild, etc.) [Throughout UST excavation, strong] Was water present in the UST excavation, soil borings, or trenches? If yes, how far below land surface (indicate location and depth)? X Did contaminated soils remain stockpiled on site after closure? If yes, indicate the stockpile location on the site map. *X Was a petroleum sheen or free product detected on any excavation or boring waters?

^{*}Per agreement with SouthDiv, Cecil Field Environmental, and Bechtel, all soil from the excavation was transported to Site 3 on base and placed on two layers of poly and covered by another double layer of poly and held down by sandbags. Soil is being stockpiled at Site 3 for future treatment/incineration. Excavation was backfilled with clean fill from Powerline Sand Inc., 8442 W. Beaver St., Jacksonville, Florida, 32220.



IX. SAMPLING METHODOLOGY



Provide a detailed description of the methods used to collect <u>and</u> store (preserve) the samples.

After the removal of UST 606, an Organic Vapor Analyzer-Flame Ionization Detector (PE PHOTOVAC MicroFid, Serial Number CZEF215) was used to screen the soils for petroleum hydrocarbon vapors. OVA headspace samples were taken in each corner and in the center of the excavation at 1' and every two feet thereafter until reaching the concrete ballast pad. In this excavation, the top of the concrete ballast pad was at 7'. UST piping soil samples were taken two feet under the piping at the mechanical connections or at the center of the piping run. OVA headspace soil samples were extracted using the backhoe bucket and sampled from the middle of the bucket. Sampling was performed in accordance with the FDFP Pollutant Storage Tank Closure Assessment Requirements and the FDEP Quality Assurance Standard Operating Procedures for Petroleum Storage System Closure Assessments.

Subsequent to backfilling excavation, a temporary monitoring well was installed at the area of highest contamination, developed, purged and sampled. Sample jars were prepared by the testing laboratory. The sample containers were filled leaving no head space and immediately capped.

The samples were marked, logged, and immediately placed in sample coolers packed with ice to maintain an approximate temperature of 4° C. Tools were thoroughly cleaned and decontaminated with organic-free soap and water after each sample.


The samples remained in the custody of SPORTENVDETCHASN until they were transferred to NPWC Pensacola Environmental Laboratory for analysis as documented in the attached Chain-of-Custody Record.


Attachment I

SITE MAP


You must supply a <u>scaled</u> site map. It should include all buildings, road names, utilities, tank and pump island locations, sample locations, extent of excavation, and any other pertinent information.

Site Maps 1, 2, 3, and 4 Temporary Monitoring Well Installation Detail Photographs 1, 2, 3, and 4













SB #	TIME	DEPTH	READING(ppm)
SB-606-1	0855	5,	32.0 - OPETRACION
SP-606-2	0920	5,	547.0
28-606-3	0933	4'	267.0
SB-606-4	0955	6'	52.0
59-606-5	1125	5,	174.0
SB-606-6	1147	4'	975.0
SB-606-7	<u> </u>		MEANG HET THERE R.E. TO VET MIR. AT F
	Ì	1	L



SS #	TIME	DEPTH	READING(ppm)
1-22	1740	1'	690
s-2	1743	3,	2380
22-3	1750	<u> </u>	4200
\$5-4	1753	3'	2071
\$5-5	1746	5'	4613
55-6	1756	5′	755
55-7	1749	7'	>5000
22-0	1758	7'	868
9-22	1800	7'	1334
22-10	1802	l'	225
11-22	1804	3′	2310
22-15	1805	5′	3015
55-13	1807	7'	2027
55-14	1809	l'	463
55-15	1811	3′	638
55-16	1812	5'	>5000
55-17	1814	7'	>5000
22-18	0944	3'	607
55-19	0946	3′	335
22-50	0948	3'	1324
1	<u> </u>		

LEGEND

- H HOLES FOUND HERE
- P POWER POLE
- S SEWER MANWAY
- SB SOIL BORING
- () SDIL SAMPLE (SS-#)



NOTE

APPROX. 20 CU YARDS OF CONTAMINATED SOIL WAS REMOVED AND TRANSFERED TO SITE 3 AT NAS CECIL FIELD.


SPORTENVDETCHASN
1899 North Hobson Ave.
North Charleston, SC
29405-2106
(803) 743-6777

Site Map 4 UST 606 NAS Cecil Field Yellow Water Weapons Area Jacksonville, FL

DWG DATE 22 MAY 97

DWG NAM

606_4



UST 606 at NAS Cecil Field




Photo 1: UST 606 exposed for removal.




Photo 2: Close up of UST 606 hole.




Photo 3: Location of two of the holes.


UST 606 at NAS Cecil Field



Photo 4: UST 606 being removed from the excavation. Note the absence of groundwater.

Attachment II

ANALYTICAL RESULTS



Certified Analytical Results Chain-of-Custody

Environmental Laboratory

Bldg. 3887, Code 920

NAS Pensacola, FL 32508 - 6500

hone (904) 452-4728/3642

JSN 922-4728/3642

Client:

SPORTENVDETCHASN Lab

Address: 1899 N. Hobson Ave.

N. Charleston, S.C. 29405-2106

Phone #: (803) 743-3239 ext. 26

- JSN 922-4728/3642		Phone #:	(803) 7	743-3239	ext. 26
FAX 922-2783	Contact:	Mr. Fre	ed McLea	n	
LAB Sample ID#	71699				
Sample Name / Location		Bidg. 606 TW-606-1			
		97CNS011-1			
Collector's Name		McElwee			
Date & Time Collected		0-/22/97 @ 10	120		
Sample Type (composite or grab)		Grab			
Analyst		J. Moore			
Date of Extraction / Initials		04/23/97 JM			
Date of Analysis		04/23/97			
Sample Matrix					
		GW		···	
Dilution			X	1	_
Compound	Į			Det.	
Name	1-	71699	units	Limit	Flags
Benzene	BDL		ug/L	1	
Bromobenzene	BDL		ug/L	1	<u> </u>
Bromochioromethane	BDL		ug/L	1	
Bromodichloromethane	BOL		ug/L	1	<u></u>
Bromoform	BDL		ug/L	2	
Bromomethane	BDL		ug/L	3	
n-Butyibenzene	BDL		ug/L	1	
sec-Butylbenzene /	BDL		ug/L	1	:
tert-Butylbenzene	BDL		ug/L	2	
Carbon Tetrachloride	BOL		ug/L	11	
'orobenzene	BDL		ug/L	1	
, iroethane	BDL		ug/L	1	
,nloroform	BDL		ug/L	1	
Chloromethane	8DL		ug/L	1	
2-Chiorotoluene *	BOL		ug/L	1	
4-Chiarataluene *	BOL		ug/L	1	
Dibromochloromethane	BDL		ug/L	1	
1,2-Dibromo-3-chloropropane *	8DL		ug/L	5	
1.2-Dibromoethane	BOL		ug/L	1	
Dibromomethane	BDL		ug/L	1	
1,2-Dichtorobenzene	BDL		ug/L	1	
1,3-Dichlorobenzene	BDL		ug/L	1	
1.4-Dichlorobenzene	BDL		ug/L	1	
Dichlorodifluoromethane	8DL		ug/L	1	
1,1-Dichloroethane	BDL		ug/L	1	
1,2-Dichloroethane	BDL		ug/L	1	
1,1-Dichloroethene	BOL		ug/L	1	
cis-1.2-Dichloroethene	BDL		ug/L	1	
rans-1.2-Dichloroethene	BOL		ug/L	1	
,2-Dichloropropane	BDL		ug/L	1	
.3-Dichtoropropane	BDL		ug/L	1	
.2-Dichloropropane	BDL		ug/L	1	
,1-Dichtoropropene	BDL		ug/L	1	
thylbenzene	BDL		ug/L	1	
Ethyl ether *	BDL		ug/L	1	
· exachlorobutadiene	BOL		ug/L	2	
-Hexanone •	BDL		ug/L	1	-
sopropylbenzene	BOL		ug/L	1	
o-isopropyitoluene	BOL		ug/L	1	

Analytical Report

Total Volatiles by Method 8260

Lab Report Number:

Sample Date:

04/22/97 04/23/97

Received Date: Sample Site:

NAS Cecil Field, FL

Job Order No.:

127 4021

Environmental Laboratory

Bidg. 3887, Code 920

NAS Pensacola, FL 32508 - 6500

hone (904) 452-4728/3642

SN 922-4728/3642

Client:

SPORTENVDETCHASN Lab

Address: 1899 N. Hobson Ave.

N. Charleston, S.C. 29405-2106

Phone #: (803) 743-3239 ext. 26

Contact: Mr. Fred McLean

Analytical Report

Total Volatiles by Method 8260

Lab Report Number:

71699 04/22/97

Sample Date: Received Date:

04/22/97 04/23/97

Sample Site: Job Order No.: NAS Cecil Field, FL

127 4021

		Contact.	1917. 1 10	o wcrean	
Compound				Det	
Name	1-	71699	units	Limit	Flags
Methylene Chloride	BDL		ug/L	1	
Methyl ethyl ketone (MEK)	BDL		ug/L	2	
Methyl isobutyl ketone (MIBK) *	BDL		ug/L	1	
Methyl-tert-butyl ether (MTBE)	BDL		ug/L	1	
Naphthalene	BOL		ug/L	11	
n-Propylbenzene	BOL		ug/L	1	
Styrene	BDL		ug/L	1	
1,1,1,2-Tetrachioroethane	BOL		ug/L	1	
1.1,2.2-Tetrachiomethane	BDL		ug/L	1	
Tetrachioroethene	BDL		ug/L	1	
Toluene	BDL		ug/L	1	
1,2,3-Trichlorobenzene	BDL		ug/L	11	
1,2,4-Trichlorobenzene	BDL		ug/L	. 1	
1,1,1-Trichloroethane	BOL		ug/L	11	
1,1,2-Trichloroethane	BDL		ug/L	11	
Trichloroethene	8OL		ug/L	1	
Trichlorofluoromethane	BOL		ug/L	1	
1,1,2-Trichloro-1,2,2-Trifluoroethane	BDL		ug/L	11	
1,2,3-Trichloropropane	BOL		ug/L	11	
1,2,4-Trimethylbenzene	BDL		ug/L	1	
1,3,5-Trimethy/benzene	BOL		ug/L	1	
Vinyl Chloride /	BDL		ug/L	11	
m.p-Xylene	BDL		ug/L	1	
n-Xylene	BDL		ug/L	1	_

SURROGATE SPIKE RECOVERIES

	Acceptance	-	
	Limits	Percent Recovery	
1.2-Dichloroethane-d4	75-133	104	
Toluene-d8	86-119	99	
Bromofluorobenzene	85-116	101	

Explanation of Flags:		
COMMENTS :		
BDL = Below Detect	on Limit. ug/L = microgram per Liter. ug/Kg = microgram per Kilogram. •	= FL HRS certification pending.
Approved		Date: 5/9/97
	Jerry Deel Caparatory Director	Report Generated

. . . .

Environmental Laboratory

Bldg. 3887, Code 920

NAS Pensacola, FL 32508 - 6500

hone (904) 452-4728/3642 JSN 922-4728/3642

Client:

SPORTENVDETCHASN Lab

Address:

1899 N. Hobson Ave.

Phone #: (803) 743-3239 ext. 26

Analytical Report

610 PAH's by Method 8270

Lab Report Number: Sample Date:

71699

N. Charleston, S.C. 29405-2106 Received Date:

04/22/97 04/23/97

Sample Site: Job Order No.: NAS Cecil Field, FL

:	127	4021

	Contact: Mr. Fred McLean				
LAB Sample ID#	1-	71699			
Sample Name / Location	Bidg. 606 TW-506-1				
<u> </u>	ł	97CNS011-1			
Collector's Name		McElwee			
Date & Time Collected		04/22/97 @ 10	20		
Sample Type (composite or grab)		Grab			
Analyst		M. Champers			
Date of Extraction / Initials		04/25/97 JJ			
Date of Analysis		04/28/97			
Sample Efatrix		GW			
Dilution			Х		1
Compound					
Name	1-	71699	units	MDL	Flags
Acenaphthene	BOL		ug/L	2	
Acenaphthylene	BDL		ug/L	2	
Anthracene	BDL		ug/L	2	
Benzo(a)anthracene	8DL		ug/L	2	1
Benzo(a)pyrene	BDL		ug/L	2	1
Benzo(b)flouranthene	BDL		ug/L	2	1
Benzo(g,h.i)perylene	BDL		ug/L	2	
Benzo(k)flouranthene	BDL	i	ug/L	3	
Chrysene	BOL	i	ug/L	2	
Dibenz(a.h)anthracene	BDL		ug/L	2	
curanthene	BOL		ug/L	2	
Leue	8DL		ug/L	2	1
naeno(1,2,3-cd)pyrene	BOL		ug/L	2	
1-Methyinaphthaiene *	BDL		ug/L	2	1
2-Methylnaphthaiene	BDL		ug/L	3	
Vaphthalene	BDL		ug/L	2	1
Phenanthrene	BDL		ug/L	2	
Pyrene	BDL		ug/L	2	T -

SURROGATE SPIKE RECOVERIES

."	Acceptance		
	Limits	Percent Recovery	
Nitrobenzene- d5	35-114	66	
2-Flourobiphenyl	43-116	75	
Terphenyl -d14	33-141	65	

Explanation of Flags:		_
COMMENTS :	Surrogate recovery limits derived from EPA OLM01.0 SOW 3/90.	
BDL = Below Detect MDL = Method detec	ion Limit. ug/L = Microgram per liter. ug/Kg = Microgram per kilogram. * = FL HRS certification limit. Practical quantitation limits (PQV) may be derived by multiplying the MDL by 4.	n pending.
Approved	by: Dees Naporatory Director	ste: 5/9/97 Report Generated

Environmental Laboratory

Bldg. 3887, Code 920

NAS Pensacola, FL 32508 - 6500

hone (904) 452-4728/3642

JSN 922-4728/3642

Client:

SPORTENVDETCHASN Lab

Address:

1899 N. Habson Ave.

N. Charleston, S.C. 29405-2106

Phone #:

(803) 743-3239 ext. 26

Analytical Report

Total Volatiles by Method 8260

Lab Report Number:

71700

Sample Date:

04/22/97

Received Date: Sample Site:

04/23/97

Job Order No.:

NAS Cecil Field, FL 127 4021



JSN 922-4/28/3642		Pnone #:			
FAX 922-2783		Contact:	Mr. Fre	d McLear	<u> </u>
LAB Sample ID#	1-	71700			
Sample Name / Location		VOA Trip Blan	ĸ		
		97CNS011-2			
Collector's Name		McElwee			
Date & Time Co. ected		04/22/97 @ 10	21		
Sample Type (composite or grab)		Grab			
Analyst		J. Moore			
Date of Extraction / Initials		04/23/97 JM			_
Date of Analysis		04/23/97			
Sample Matrix		GW			
Dilution			X	1	
Compound				Det.	
Name	1-	71700	units	Limit	Flags
Benzene	BOL		ug/L	1	
Вготореплене	BDL		ug/L	1	L
Bromochioromethane	BDL		ug/L	1	
Bromodichioromethane	BOL		ug/L	1	
Bromoform	BOL		ug/L	2	
Bromomethane	BDL		ug/L	3	
n-Buty/benzene	BDL		ug/L	1	
sec-Butylbenzene	BOL		ug/L	1	
tert-Butylbenzene	BOL		ug/L	2	
Carbon Tetrachloride	BDL		ug/L	1	
hlorobenzene	BDL		ug/L	1	
loroethane	BDL		ug/L	1	
hioroform	BOL		ug/L	1	
Chloromethane	BDL		ug/L	1	
2-Chiorotoluene *	BDL		ug/L	1	
4-Chlorotoluene *	BOL		ug/L	1	
Dibromochioromethane	BDL		ug/L	1	
1,2-Dibromo-3-chloropropane *	BDL BDL		ug/L	5i	
1,2-Dibromoethane Dibromomethane	BOL		ug/L ug/L	1	
1.2-Dichlorobenzene	BOL		ug/L	1	
1,3-Dichlorobenzene	BDL		ug/L	1:	
1,4-Dichlorobenzene	BOL		ug/L	1	
Dichlorodifluoromethane	BOL		ug/L	1	
1,1-Dichloroethane	80L		ug/L	1	
1.2-Dichloroethane	BDL		ug/L	1	
1,1-Dichloroethene	BOL		ug/L	1	
cis-1.2-Dichloroethene	80L		ug/L	1	
trans-1.2-Dichloroethene	BOL		ug/L	1	
1.2-Dichloropropane	BDL		ug/L	1.	
1,3-Dichtoropropane	BDL		ug/L	1	
2,2-Dichtoropropane	BDL		ug/L	1	
1,1-Dichtoropropene	BOL		ug/L	1	
Ethylbenzene	BDL		ug/L	1	
Ethyl ether *	80L		ug/L	1	
Hexachlorobutadiene	BDL		ug/L	2	
2-Hexanone *	BDL		ug/L	1	
lsopropyibenzene	BOL		ug/L	1	
p-isopropyitoluene	BOL		ug/L	1	

Environmental Laboratory

Bldg. 3887, Code 920

NAS Pensacola, FL 32508 - 6500 Phone (904) 452-4728/3642

SN 922-4728/3642

Client:

Phone #:

SPORTENVDETCHASN Lab

Address: 1899 N. Hobson Ave.

N. Charleston, S.C. 29405-2106

(803) 743-3239 ext. 26

Contact: Mr. Fred McLean

Analytical Report

Total Volatiles by Method 8260

Lab Report Number:

71700 04/22/97

Sample Date:

04/23/97

Received Date: Sample Site: Job Order No.:

NAS Cecil Field, FL

127 4021

Compound				Det	
Name	1-	71700	units	Limit	Flags
Methylene Chloride	BDL		ug/L	1	
Methyl ethyl ketone (MEK)	BDL		ug/L	2	
Methyl isobutyl ketone (MIBK) *	BOL		ug/L	1	
Methyl-tert-butyl ether (MTBE)	BOL		ug/L	1.	
Naphthalene	80L		ug/L	1	
n-Propyibenzene	8DL		ug/L	1	
Styrene	BOL		ug/L	1	
1,1,1,2-Tetrachloroethane	BOL		ug/L	1	
1,1,2.2-Tetrachioroethane	BOL		ug/L	1	
Tetrachioroethene	BDL		ug/L	1	
Toluene	BDL		ug/L	1	
1,2,3-Trichlorobenzene	BDL		ug/L	 1	
1,2,4-Trichlorobenzene	8DL		ug/L	1	
1.1,1-Trichloroethane	BDL		ug/L	1	
1,1,2-Trichloroethane	8DL		ug/L	11	
Trichloroethene	BOL		ug/L	1	
Trichiorofluoromethane	BOL		ug/L	1	
1,1,2-Trichloro-1,2,2-Trifluoroethane	BOL		ug/L		
1,2,3-Trichloropropane	BDL		ug/L	1	
1,2,4-Trimethylbenzene	BOL		ug/L	1	
1,3,5-Trimethylbenzene	BOL		ug/L	1	
Vinyl Chloride /	BDL		ug/L	1	
m,p-Xylene	BOL		ug/L	1	
n-Xylene	BDL	1	ug/L	1	

SURROGATE SPIKE RECOVERIES

•	Acceptance		
<u></u>	Limits	Percent Recovery	
1.2-Dichloroethane-d4	75-133	101	
Toluene-d8	86-119	100	
Bromofluorobenzene	85-116	100	

Explanat	ion of Flags:			
			<u></u>	
	COMMENTS :			
			· · ·	
				
	BDL = Below Detection Lin	nit. ug/L = microgram per Liter. ug/Kg = microgram per Kilogram.	* = FL HRS certification pe	ending.
	Approved by :	Janes Vinne		£ 12 12 T
	Approved by .	Vary Dave Laboratory Director	Date:	5/9/97 Report Generated

CHAIN OF CUSTODY/REQUEST FOR ANALYSIS

NPWC Environmental I	aboratory		·		.' Report Required?		No. OC Server	
Bidg. 3887. Code 920	,	Requester:	SPORTE	NVDETCHA:	,	<u> </u>		
NAS Pensacola, Fl. 32508		Address:		obson Avenue	Lab ID Harmon:	a	6018	
				. S.C. 29405 - 21			122127	
Ph#: (904) 452-4728/3842						_4	12219+	
OSN: 922-4728/3642		Phone #:	(803) 743-32		Removed Out 4.			
FAX: (904) 452-2799/2387		Contact	Mr. Fred McL	ean	Sampro 6244	NA	S CECIL FI	ELO
		Job Order #: /	2		Lab Due Date:			
Sample IO #	ظعا	10-7-16-99	1-7-170	00 00-	04-		lotenc .	
Samble Name		197CH 5011-	1 97CNS01	1-2				
of Location		7W-606-		P				
Samples by		MUELWER		EE				
Collection	Oste	4/22/97	4/22/		i	7		
Oste/Trne	Time	1020	102			-		
	1	! GW	16W	- 		-		
Sample Matrix		.: 0 40	1 00	<u> </u>	!	<u> </u>		
GROUP PARAMETERS						Billing	Contamers	Preservativals)
by Method Name	METHOD #	X Borne O F	Borde (C)	Ft X Botto	OF X Botto OF	58.51	Uould/Selld	Used (Counte)
HW Charact, (complete)	EPA SW 646	1 1		<u> </u>		1 38.31	300 00000 250mi/4 cs.	3 to bear
Rescurity (Cyanica & Sunger	EPA SW-846	1 1				1 4	1U4 cz.	ec ec
Corroseer (pri	SW 846 9040/9045	<u> </u>				0.5	250mi/4 eq.	- C
Tozon (TCLP) corrende	EPA 6W-846	1 1	ii			53	Seeber	300 00000
Toxicity (TCLP) complete	EPA SW-646	i i	1 1	1 1		1 53	San bear	San bear
Toxicity (TCLP) less PerlyHerts	EPA 5W-846	ii	1 1			35	See bear	See 4
TCUP SNA Estrecuping	SW 848 6270	1 1	1 1	1		18	1L±3/4 eg.	₽ C \$3,
TCLP Acrd Extractions	SW 646 8270	1 1	1			1 0	1Uz3/4 ez.	FC
TCLP B/N Extractions	SW 646 6270	1	1 1	1		10	1Lx3/4 ex.	e c
TCLP Persons	5W 848 8080	1 1		1		as!	1Lx3/4 cz.	FC
TCUP Herocom	SW 846 8150	1	1 1			esi	11.23/4 cm.	₽ C
TCUP Volume	SW 646 6200	1	1 1			toi	40 mt x 4/4 cc.	-c
TCUP Metale (6)	EPA SW-048	i l	1 1			101	500 me/4 est.	l ec
F001 - F705 Solvents	EPA SW-646	1 1				241	10:28:40mm3/18 az.	-c
Total Voletims	SW 846 6260	1 1	!]	<u> </u>		1 75	40 mes44 ez.	HC 10 0H < 2/4" C
BTEX & Nacorthalene + MTBE	SW 848 8280	IX 197CHSOIL	-1 X 97CNS	DII-21		1 91	40 mis 4/4 cz.	HC3 10 BH < 2/4" C
Total SNA Extractions	SW 646 8270	1 1	<u> </u>	<u> </u>		16	1Ux2/16 ex.	FC
PAHE	SW 846 8270	1X1976180	1-1			•	1Uz2/16 ex.	rc
PCB's n OI	SW 646 8080	1 }	1			1 3	40 me/4 est.	None
PCB's in Weller/SolvWides	2W 846 8080	1 1			<u> </u>	1 4	1U4 cz.	None
Total ACRA Metall (5)	EPA 5W-648	1 1	1 1			#1	500 m/4 cc.	HNO, 10 8H < 2
Asbertos i Bulki	<u> </u>		1 1			l esi	Zhine	None
TPH (IR)	EPA 418.1					1 2	1Us2/4 ez	HC 10 9H < 2/4" C
OI & Gresse	EPA 413 1	<u> </u>				1 21		HC 10 9H < 2/4" C
Lead in Perit	SW 848 6010		1 1			-!!		Name
Total Ordanic Melogene	EPA SW-046	1 1				_	ZOWIANA CE	ec .
Other	<u> </u>	1 110F6				1		1
	1	1 1 GOFL		9		1		<u> </u>
	<u> </u>		! !					<u> </u>
	<u> </u>					1	' 	
	1	1 1				-		
	1	1 ł	<u> </u>	<u> </u>		-		<u> </u>
Comments				<u></u>				
								<u> </u>
Renoushed by:	44	لسحولس			Description 4-23.	nac	alec)	··-
	4(22)		his		0 mortione 4.23.	97	1103	<u> </u>
Cate/Tyme	- M-L	7 1 / 70	110 3					

Attachment III

Certificate of Disposal (tank)
Disposal Manifest (fuel)

UST Certificate of Disposal

CONTRACTOR

Supervisor of Shipbuilding, Conversion and Repair, USN Portsmouth, VA Environmental Detachment Charleston 1899 North Hobson Avenue North Charleston 29405-2106

Telephone (803) 743-6482

TANK ID & LOCATION

Building 606, NAS Cecil Field, Main Rd., Yellow Water Weapons Area, Jacksonville, FL 32215-0101

DISPOSAL LOCATION

NAS Cecil Field Recycling Center, Building 805 Jacksonville, FL, 32215-0101

TYPE	OF	TANK
Fuel oil		

SIZE (GAL)

CLEANING/DISPOSAL METHOD

The tank was cut open on both ends, cleaned with a steam cleaner, cut into sections, and disposed of as recyclable scrap metal.

DISPOSAL CERTIFICATION

I certify that the above tank has been properly cleaned and disposed of as recyclable scrap metal.

71. Lc20ee 1 5/22/97
T. L. McElwee (Date)



	inc.	
NON-HAZARDOUS	1. Generator's US EPA ID No. Manufes:	
WASTE MANIFEST	1. Senerators US EPA ID No. Manufes Cocument	No. of / 4/- /K/- 57
J. Generator's Name and Mailing Address		
VAUAL AIR STATION: CE CIL FO	IRD SCE Siver NO 494	43
JACKSONVIIIE,	FUI 33275-0106	
4. Generator's Phone (Cod) >78 - 1	1030	
	6. US EPA ID Number	Crecit
7. Transporter 2 Company Name	6. US EPA ID Number	3 0.0
	o con a number	Paid
9. Designated Facility Name and Site Address	10. US EPA ID Number	A Transporters Phone-70-344-7110
Georgia Petroloum, Inc.	GAD# 981222433	B. Transporters Phone
1612 Jemes P. Regers Circle Valciosta, Georgia 31601 6	1	C. Fecility's Phone
		912-244-9110
11. Waste Shipping Name and Description		12. Containers 13. 14. Total Unit
2		No. Type Quantity WVVoi
NON HAZ 1	DIRTY DIESE	17 200
b	7	
1/1/1/1/2	1. 1/6	
WON HAZ (L	19(4db) (0++50	6/ 75/0/
DIESEL) NI	05 01 / 1/1 199	7
4		
dictional Descriptions for Materials Listed Above		E. Handling Codes for Wastes Listed Above
API 34.3 VIS	32 PUN (2170)	
CHLOR <u>450</u>		
15. Special Hendling Instructions and Additional Inform	nation	
in the event of an emergency	call 012-24 1-9110 Mon - Fri 8-5 or	- 019-949 (900) and time
, , , , , , , , , , , , , , , , , , ,	The state of the Rich of the Bas of	a re-z-m-, ou r anyume.
№ .	•	
15. GENERATOR'S CERTIFICATION: I compy the mat	\ 	
Printed/Typed Name	/ Signature	puletions for reporting proper disposal of Hezardous Waste.
1185/11 A VI: m		Month Day Year
17. Transcorter 1 Actinowiedgement of Flecelot of Mati	arais Carlos	1000 1117
Printed Types Name	Signatura 11	Month Day Year
Freddy Norms	tell 1	04 1497
18 Transcorter 2 Actnowledgement of Recipi of Mate		
Printing Types name	Signature	Moruh Day Yeer
19. Discrepancy indicaten Space		
Portot #1/25000 12.	Sypl. Free water Huss	6% water in 1 Layer
(any) (2)(3)(4) so	cont loss 12	ulator
O. Facility Owner or Operator: Certification of receipt of	weste materials covered by this manifest except as noted in	item 19,
		1 11
.tad/Typed Name	Signature	Month Day Year
(3eNO (78)	HIUSS Lene	Bally 641587
male page	TRANSPORTER #1	Control of the second



Florida Department of Environmental Regulation

Twin Towers Office Bldg. ● 2600 Blair Sione Road. ● Tallahassee, Florida 32399-2400

DER system # 17-761 900(6)
From Lay Cosure Assessment Form
- Emiliar Com December 10, 1990
DER ADDICATOR No
-moin to DEA



Closure Assessment Form

Owners of storage tank systems that are replacing, removing or closing in place storage tanks shall use this form to demonstrate that a storage system closure assessment was performed in accordance with Rule 17-761 or 17-762, Florida Administrative Code. Eligible Early Detection Incentive (EDI) and Reimbursement Program sites do not have to perform a closure assessment.

Please Print or Type Complete All Applicable Blanks

1. Date:	
4. Facility Name: Building 606, EM Dining Facility 5. Facility Owner: Naval Air Station Cecil Field 6. Facility Address: Bldg 606, Main Rd., Yellow Water Weapons Area 7. Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, Jacksonville, FL 32215 8. Telephone Number: (904) 778–5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 12. Were the Tank(s): (Circle one) A. Replaced 8. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 1 14. Age of Tanks:	
5. Facility Owner: Naval Air Station Cecil Field 6. Facility Address: Bldg 606, Main Rd., Yellow Water Weapons Area 7. Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, Jacksonville, FL 32215 8. Telephone Number: (904) 778-5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 12. Were the Tank(s): (Circle one) A. Replaced 3. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 1 14. Age of Tanks: Facility Assessment Information	·
6. Facility Address: Bldg 606, Main Rd., Yellow Water Weapons Area 7. Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, Jacksonville, FL 32215 8. Telephone Number: (904) 778–5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 12. Were the Tank(s): (Circle one) A. Replaced 9. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 1 14. Age of Tanks: Facility Assessment Information	···
7. Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, Jacksonville, FL 32215 8. Telephone Number: (904) 778–5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 2. Were the Tank(s): (Circle one) A. Replaced S. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 1 14. Age of Tanks: Facility Assessment Information	· · · · · · · · · · · · · · · · · · ·
7. Mailing Address: N.P.W.C., Box 101, Cecil Field Zone, Jacksonville, FL 32215 8. Telephone Number: (904) 778–5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 2. Were the Tank(s): (Circle one) A. Replaced S. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 1 14. Age of Tanks: Facility Assessment Information	·
8. Telephone Number: (904) 778–5620 9. Facility Operator: Llovd Cruz 10. Are the Storage Tank(s): (Circle one or both) A. Aboveground or 3. Underground 11. Type of Product(s) Stored: Fuel oil 2. Were the Tank(s): (Circle one) A. Replaced 8. Removed C. Closed in Place D. Upgraded (13. Number of Tanks Closed: 14. Age of Tanks: Facility Assessment Information	-0101
11. Type of Product(s) Stored: Fuel oil 2. Were the Tank(s): (Circle one) A. Replaced B. Removed C. Closed in Place D. Upgraded (stanks): 14. Age of Tanks: Facility Assessment Information	·
2. Were the Tank(s): (Circle one) A. Replaced B. Removed C. Closed in Place D. Upgraded (14. Age of Tanks: Facility Assessment Information	
Facility Assessment Information	(aboveground tanks only)
1. Is the facility participating in the Fiorida Petroleum Liability Insurance and Restoration 2. Was a Discharge Reporting Form submitted to the Department? 11 yes, When: notification made by Where: Cecil Field Env., 23 Is the depth to ground water less than 20 feet?	
3. Is the depth to ground water less than 20 feet? 4-16-97 4. Are monitoring wells present around the storage system?	7
If yes, specify type: Water monitoring Vapor monitoring 5. Is there free product present in the monitoring wells or within the excavation? 6. Were the petroleum hydrocarbon vapor levels in the soils greater than 500 parts per manufacturers.	nillion for gasoline?
Specify sample type: Vapor Monitoring wells Soil sample(s) 7. Were the petroleum hydrocarbon vapor levels in the soils greater than 50 parts per mil	illion for diesel/kerosene?
Specify sample type:	owable state target levels?
9. If a used oil storage system, did a visual inspection detect any discolored soil indicating 10. Are any potable wells located within 1/4 of a mile radius of the facility? 11. Is there a surface water body within 1/4 mile radius of the site? If yes, indicate distance:	no a release?

DE# Form17-761.900761	
from Tax. Closure Assessment Form	
Encorre Com December 10, 1990	
DER Aggregation to C	
/~~~ A & &	/En.

12. A detailed drawing or skerch of the facility that includes the storage system location, monitoring wells, buildings, storm drains, sample locations, and dispenser locations must accompany this form.

13. If a facility has a pollutant storage tank system that has both gasoline and kerosene/diesel scred on site, both EPA Method 602 and EPA Method 610 must be performed on the ground water samples obtained.

14. Amount of soils removed and receipt of proper disposal.

15. If yes is answered to any one of questions 5-9, a Discharge Reporting Form 17-761,900(1) indicating a suspected release shall be submitted to the Department within one working day.

16. A copy of this form and any attachments must be submitted to the Department's district office in your area and to the locally administered program office under contract with the Department within 60 days of completion of tank removal or filling a tank with an inert material.

Signature of Owner		Date
~ -0) \sim 0	4	1/13/0-
Signature of Person Performing Assessment	<u> </u>	

Environmental Specialist

Title of Person Performing Assessment

State Ground Water Target Levels That Affect A Pollutant Storage Tank System Closure Assessment

State ground water target levels are as follows:

- 1. For gasoline (EPA Method 602):
 - a Benzene

1 ug/l

b. Total VOA

50 ug/l


- Benzene
- Toluene
- Total Xvienes
- Ethylbenzene
- c. Methyl Test-Buryl


50 ug/l

Ether (MTBE)

- 2. For kerosene/desel (EPA Method 510):
 - Polynuclear Aromatic Hydrocarbons (PAHS)
 (Best achievable detection limit, 10 ug/l maximum)







(29

82 #	TIME	DEPTH	READING(ppm)
1-22	1740	ľ	690
22-S	1743	3'	2380
\$\$-3	1750	ľ	4200
55-4	1753	3′	2071
52-5	1746	5'	4613
22-6	1756	<u>5'</u>	755
55-7	1749	7'	>5000
52-8	1758	7'	898
52-9	1800	7'	1334
55-10	1805	1'	225
22-11	1804	3,	5310
22-12	1805	5'	3015
55-13	1807	7'	2027
55-14	1809	1'	463
55-15	1811	3,	630
22-16	1815	5'	>5000
55-17	1814	7'	> 5000
81-22	0944	3,	607
22-19	0946	3,	335
22-50	0948	3′	1324
L	1	<u> </u>	


4 -	НΠІ	F.S	FOUND	HFR

6 - BOMEK BOLE H - HOLEZ FOOND HI

S - SEWER MANWAY

SB - SOIL BORING

(\$2-#)



NOTE:

(18)

(17(16)(15)(14)

(13(12(11)(10

SB-606-2, 3, 4

SB-606-1

UST 606

APPROX. 20 CU YARDS OF CONTAMINATED SOIL WAS REMOVED AND TRANSFERED TO SITE 3 AT NAS CECIL FIELD.


SPORTENVDETCHASN 1899 North Hobson Ave. North Charleston, SC 29405-2106 Pm (803) 743-6777

H

Site Map 2 UST 606 NAS Cecil Field Yellow Water Weapons Area Jacksonville, FL

DWG DATE:22 MAY 97

DWG NAME 606_4



APPENDIX B
SOIL ANALYTICAL DATA

NAS CECIL FIELD -- TANK 606 SOIL DATA -- KEROSENE ANALYTICAL GROUP -- REPORT REQ NO. 9947

Lab Sample Number: Site Locator Collect Date:	VALUE	A8D1701010 UST GREY CEF-606-SB1 15-APR-98 QUAL UNITS	DL	VALUE	ABD1701010 UST GREY CEF-606-SB2 15-APR-98 QUAL UNITS	DL	
--	-------	--	----	-------	--	----	--

ST GREY						
Benzene	1.1 U	ug/kg	1.1	1.2 U	ug/kg	1.2
Ethylbenzene	1.1 U	ug/kg	1.1	1.2 U	ug/kg	1.2
Toluene	1.1 U	ug/kg	1.1	1.2 U	ug/kg	1.2
Xylenes (total)	1,1 U	ug/kg	1,1	1.2 U	ug/kg	1.2
Acenaphthene	230 U	ug/kg	230	4700 U	ug/kg	4700
Acenaphthylene	230 U	ug/kg	230	4700 U	ug/kg	4700
Anthracene	230 Ū	ug/kg	230	4700 U	ug/kg	4700
Benzo (a) anthracene	23	ug/kg	5.7	120 U	ug/kg	120
	33 29	ug/kg	5.7	120 U	ug/kg	120
Benzo (a) pyrene	32	ug/kg	5.7	120 U	ug/kg	120
Benzo (b) fluoranthene	20	ug/kg	5.7	120 U	ug/kg	120
Benzo (g.h.i) perylene	15	ug/kg	5.7	120 U	ug/kg	120
Benzo (k) fluoranthene	28	ug/kg	23	470 U	ug/kg	470
Chrysene	28 J	ug/kg	5.7	120 Ŭ	ug/kg	120
Dibenzo (a.h) anthracene			5.7	120 U	ug/kg	120
Fluoranthene		ug/kg	230	4700 U	ug/kg	4700
Fluorene	230 U	ug/kg		120 U	ug/kg ug/kg	120
Indeno (1,2,3-cd) pyrene	21 J	ug/kg	5.7	4700 U		4700
Naphthalene	230 U	ug/kg	230		ug/kg	4700
Phenanthrene	230 U	ug/kg	230	4700 U	ug/kg	
Pyrene	77	ug/kg	5,7	120 U	ug/kg	120
그 그 이번 그는 그는 물이 없는데 있었다. 유명이 그 그는 그						300
LA PRO					41	1.0
TPH C8-C40	19	mg/kg	11	35	mg/kg	12
■		er or had some bling daring	280 PM 490 PM			